DMR Copy of Record

Permit																				
Permit #:	MA	R054014			Permittee:		Bos	ton Cor	ncrete Cor	poration				Facility:	E	BOSTO	оо ис	NCR	ETE CORPORAT	TON
Major:	No			Permittee Address:			706 Broadway Street Lowell, MA 01854						Facility Location:			706 BROADWAY STREET LOWELL, MA 01854				
Permitted Feature: 001 External Outfall				Discharge:				001-E2 Concrete and Gypsum Product Manufacturers												
Report Dates &	Status			·																
Monitoring Perio	od: Fro	om 01/01/20 t	03/31/20		DMR Due D	ate:	05/2	28/20						Status:	ı	NetDM	IR Vali	idate	d	
Considerations	for Form Cor	mpletion																		
Principal Execut	tive Officer																			
First Name:	She	erry			Title:		Sr F	Project I	Manager					Telephone:	9	78-27	'0-009 ⁴	4		
Last Name:	Albe	ert																		
No Data Indicato	or (NODI)																			
Form NODI:																				
	meter	Monitor	ng Location	Season #	Param. NODI		D!!!!! 4		ty or Loadir		-11- 01161-	4 1/21 4 6		y or Concentralue 2 Qualific				# of E	x. Frequency of Ana	lysis Sample Typ
Code	Name					Sample	auaimer 1	value 1	Qualifier 2	value 2 U	nts Quanne	er i value i c	auaimer 2 v	alue 2 Qualific	2100.0		Jnits - mg/L		01/90 - Quarterly	GR - GRAB
X ₀₀₅₃₀ Solids	s, total suspen	nded 1 - Effl	uent Gross	0		Permit Req. Value NODI								<=	100.0 MAXIM	UM 19	- mg/L	1	01/90 - Quarterly	GR - GRAB
						Sample								=	20.1		- mg/L		01/90 - Quarterly	GR - GRAB
	X ₀₁₀₄₅ Iron, total [as Fe]		ent Gross	0		Permit Req. Value NODI								<=	1.0 MAXIMUN	vi 19	- mg/L	. 1	01/90 - Quarterly	GR - GRAB
Submission Not	te w does not co	ontain any valu	es for the	Sample n	nor Effluent T		n none of	f the fol	lowing fiel	ds will be	submitted	d for that ro	ow: Units,	Number of E	xcursions, Fre	quenc	cy of Ar	nalysi	is, and Sample Ty	/pe.
Submission Not f a parameter rov Edit Check Error Parame	v does not co	ntain any valu		Sample n	nor Effluent T		n none of		lowing fiel	ds will be	submitted	d for that ro		Number of E	xcursions, Fre	equenc	cy of Ar	nalysi	is, and Sample Ty	rpe. Acknowledge
Submission Note If a parameter row Edit Check Error Parame Code N	v does not conter seter	Monitoring L	ocation		Field	rading, ther	Туре	e					De	escription						Acknowledge
Submission Not f a parameter rov Edit Check Error Parame	w does not con rs ster lame al suspended	Monitoring L	ocation Quarter Quarte	uality or Co		Frading, ther	Type 3 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota	w does not con rs ster lame al suspended	Monitoring Lo	ocation Quarter Quarte	uality or Co	Field oncentration s	Frading, ther	Type 3 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments	w does not con rs ster lame al suspended	Monitoring Lo	ocation Quarter Quarte	uality or Co	Field oncentration s	Frading, ther	Type 3 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note of a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total	w does not con rs eter lame	Monitoring Lo	ocation Quarter Quarte	uality or Co	Field oncentration s	Frading, ther	Type 3 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note of a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Attachments	v does not contrs ter lame al suspended [as Fe]	Monitoring Lo	ocation Quarter Quarte	uality or Co	Field oncentration s	Frading, ther	Type 3 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note of a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Attachments Io attachments.	w does not con rs ter lame al suspended [as Fe]	Monitoring Lo	ocation Quarter Quarte	uality or Co	Field oncentration s	Frading, ther	Type 3 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Attachments Io attachments. Report Last Save	w does not con rs ter lame al suspended [as Fe]	Monitoring Lo	ocation Ocation Ocation Ocation	uality or Co	Field oncentration s	Frading, ther	Type 3 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Attachments Io attachments. Report Last Save	w does not con rs ter lame al suspended [as Fe]	Monitoring Lo	ocation ass Quess Quess Questions	uality or Co	Field oncentration soncentration s	Frading, ther	Type 3 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Attachments Io attachments. Report Last Sav. Boston Concrete User: Name: E-Mail:	w does not con rs ter lame al suspended [as Fe]	Monitoring Lo	SAL She salb	uality or Co uality or Co BERT1 erry Albe pert@sake	Field oncentration soncentration sert ent	Frading, ther Sample Value Sample Value	Type 3 Soft 5 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Attachments Io attachments. Report Last Sav. Boston Concrete User: Name: E-Mail: Date/Time:	w does not contrs ter lame al suspended [as Fe]	Monitoring Lo	SAL She salb	uality or Co uality or Co BERT1 erry Albe pert@sake	Field oncentration soncentration s	Frading, ther Sample Value Sample Value	Type 3 Soft 5 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Attachments Io attachments. Report Last Sav. Boston Concrete User: Name: E-Mail:	w does not contrs ter lame al suspended [as Fe]	Monitoring Lo	SAL She salt 202	LBERT1 erry Albeoert@sake	Field oncentration soncentration sert ent	Frading, ther Sample Value Sample Value	Type 3 Soft 5 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Io attachments Io attachments User: Name: E-Mail: Date/Time: Report Last Sign User:	w does not contrs ter lame al suspended [as Fe]	Monitoring Lo	SAL She salb 202	LBERT1 erry Albert@sake 0-09-18	Field oncentration soncentration sert ent environment	Frading, ther Sample Value Sample Value	Type 3 Soft 5 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Attachments Io attachments. Report Last Sav. Boston Concrete User: Name: E-Mail: Date/Time: Report Last Sign User: Name:	w does not contrs ter lame al suspended [as Fe]	Monitoring Lo	SAL She salt She	LBERT1 Perry Albeotert@sake 0-09-18 LBERT1 Perry Albeoterty	Field oncentration soncentration sert environment 10:22 (Time	Frading, ther Sample Value Sample Value al.com	Type 3 Soft 5 Soft	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes
Submission Note If a parameter row Edit Check Error Parame Code N 00530 Solids, tota 01045 Iron, total Comments Io attachments Io attachments User: Name: E-Mail: Date/Time: Report Last Sign User:	w does not contrs ter lame al suspended [as Fe]	Monitoring Lo	SAL She salk	LBERT1 Perry Albeort@sake	Field oncentration soncentration sert ent environment	Frading, there Sample Value Sample Value ral.com e Zone: -04:	Type 3 Soft 3 Soft 000)	The p	provided sa	mple valu	e is outside	e the permit	Do limit. Pleas	escription e verify that the	ne value you ha	ve prov	vided is	corre	ct. (Error Code: 1)	Acknowledge Yes